



Date: January 15, 2017

**PRODUCT CHANGE NOTIFICATION # 10038**

**Notification of:** Part number change

**Date Change Effective:** January 17, 2017

**Explanation of change (from, to):**

Part number change	<u>from</u>	<u>to</u>
	ZEC00SAAN-M47	LEC00SAAN-M47 (DWG 12839)
	ZEC00SFAN-M47	LEC00SFAN-M47 (DWG 12839)
	ZIC00SAAN-M47	LIC00SAAN-M47 (DWG 12839)
	ZIC00SFAN-M47	LIC00SFAN-M47 (DWG 12839)
	ZEC00DAAN-M47	LEC00DAAN-M47 (DWG 13181)
	ZEC00DFAN-M47	LEC00DFAN-M47 (DWG 13181)
	ZIC00DAAN-M47	LIC00DAAN-M47 (DWG 13181)
	ZIC00DFAN-M47	LIC00DFAN-M47 (DWG 13181)

**Reason for change:** part number letter code for insulator LCP is redefined.

**Anticipated impact on fit, form, or function (positive/negative):** Positive

**Parts/Products affected:** .100" contact center continuous pin header series

**Parts prior to change will remain active for purchase?**

Yes  No

**New or revised parts are interchangeable to the previous part applications?**

Yes  No

**Engineering Approval:**

**(Signature)**

Ken Stark

**(Printed Name)**

Distribution: Website, Distributors, Customers, Internal  
Information regarding this change notification and other previously issued change notifications can be found on our website: [www.sullinscorp.com/techcenter](http://www.sullinscorp.com/techcenter). If you have any questions or concerns, please contact us at [Support@sullinscorp.com](mailto:Support@sullinscorp.com) or call us at (760) 744-0125.

Sincerely,  
**Sullins Connector Solutions**