



Date: January 15, 2017

PRODUCT CHANGE NOTIFICATION # 10038

Notification of: Part number change

Date Change Effective: January 17, 2017

Explanation of change (from, to):

Part number change	<u>from</u>	<u>to</u>
	ZEC00SAAN-M47	LEC00SAAN-M47 (DWG 12839)
	ZEC00SFAN-M47	LEC00SFAN-M47 (DWG 12839)
	ZIC00SAAN-M47	LIC00SAAN-M47 (DWG 12839)
	ZIC00SFAN-M47	LIC00SFAN-M47 (DWG 12839)
	ZEC00DAAN-M47	LEC00DAAN-M47 (DWG 13181)
	ZEC00DFAN-M47	LEC00DFAN-M47 (DWG 13181)
	ZIC00DAAN-M47	LIC00DAAN-M47 (DWG 13181)
	ZIC00DFAN-M47	LIC00DFAN-M47 (DWG 13181)

Reason for change: part number letter code for insulator LCP is redefined.

Anticipated impact on fit, form, or function (positive/negative): Positive

Parts/Products affected: .100" contact center continuous pin header series

Parts prior to change will remain active for purchase?

Yes No

New or revised parts are interchangeable to the previous part applications?

Yes No

Engineering Approval:

(Signature)

Ken Stark

(Printed Name)

Distribution: Website, Distributors, Customers, Internal
Information regarding this change notification and other previously issued change notifications can be found on our website: www.sullinscorp.com/techcenter. If you have any questions or concerns, please contact us at Support@sullinscorp.com or call us at (760) 744-0125.

Sincerely,
Sullins Connector Solutions