

Date: 8/19/2020

PRODUCT CHANGE NOTIFICATION #10046

Notification of: .100" & .156" contact center Male connector part numbers discontinued.

Date Change Effective: 8/19/2020

Explanation of change:

Remove 'Y' plating (.000030" gold on contact surface, .000005" gold overall)

Remove 'S' plating (.000010" gold plating overall)

DISCONTINUED	DISCONTINUED	Drawing #
YC _M(MR, MN)_	_SC_ _M(MR, MN)_	C11050
YC _M(MW, MS, MM)_	_SC_ _M(MW, MS, MM)_	C11051
YC _M(MA,MV,MB,MD,MJ,MK)_ (OMIT, -S189)	_SC_ _M(MA,MV,MB,MD,MJ,MK)_ (OMIT, -S189)	C11052
YC _M(MW, MS, MM)N-S1998	_SC_ _M(MW, MS, MM)N-S1998	C12781
YM _M(MR,MN)_	_SM_ _M(MR,MN)_	C11074
YM _M(MW,MS,MM)_	_SM_ _M(MW,MS,MM)_	C11075
YM _M(MA,MV,MB,MD,MJ,MK)_ (OMIT, -S189)	_SM_ _M(MA,MV,MB,MD,MJ,MK)_ (OMIT, -S189)	C11076
YM _M(MW,MS,MM)_ -S1793	_SM_ _M(MW,MS,MM)_ -S1793	C12414
YM _MMM_-S1805	_SM_ _MMM_-S1805	C12441

Reason for change:

(1) No longer offer 'Y' & 'S' plating on Male connector.

Anticipated impact on fit, form, or function: None

Parts/Products affected: .100" & .156" Contact Center, Male connector

Parts prior to change will remain active for purchase?

Yes ___ No X

New or revised parts are interchangeable to the previous part applications?

Yes X No ___

Engineering Approval:



Truong Tran

8/19/2020

(Signature)

(Printed Name)

(Date)

Distribution: Website, Distributors, Customers, Internal

Information regarding this change notification and other previously issued change notifications can be found on our website: www.sullinscorp.com/techcenter. If you have any questions or concerns, please contact us at Support@sullinscorp.com or call us at (760) 744-0125.

Sincerely,
Sullins Connector Solutions