


Product Change Notification #10052

Date: 10/10/2024

Notification of: Increased Standoffs from 1 to 4 on the termination side of the male header.

Date Change Effective: 10/10/2024

Explanation of change (from, to):



Reason for change: Improvement on the 1 & 2 positions (cut) header sit flat on the PCB.

Anticipated impact on fit, form, or function (positive/negative): Positive.

Parts/Products affected:

__C__S(AA, AB, AC, AD, AE, AF, AG, AH, AI, AJ, AK, FA, FB, FC, FD, FE, FF, FG, FH, FI, FJ, ZA, ZB, ZC, ZD, ZI, ZJ, ZO, ZQ, ZR)N - OMIT, M500, M594 (drawing # C10436)

__C__S(BA, BB, BC, BD, BE, BH, BI, BJ, GA, GB, GC, GD, GE, GF, DA)N - M71, M509, M595 (drawing # C11432)

__C__S(AB, FB, ZS, ZT)N - M30, M508, M596 (drawing # C10058)

__C__SAAR – OMIT, M500, M594 (drawing # 11110)

__C__SAAN-M85 (drawing # C13843)

__C__SBAN-SM650 (drawing # C13828)

__C__S(AA, AB, AC, AD, AE, AF, AG, AH, AI, AJ, AK, FA, FB, FC, FD, FE, FF, FG, FH, FI, FJ, ZA, ZB, ZC, ZD, ZI, ZJ, ZO, ZQ, ZR)N – M105, M597 (drawing # C12721)

__C__SZSN-M623 (drawing # C13578)

Parts remain active for purchase?

Yes No

New or revised parts are interchangeable to the previous part applications?

Yes No

Engineering Approval:



Truong Tran

10/10/2024

(Signature)

(Printed Name)

(Date)

Distribution: Website, Distributors, Customers, Internal

Information regarding this change notification and other previously issued change notifications can be found on our website:

www.sullinscorp.com/techcenter. If you have any questions or concerns, please contact us at Support@sullinscorp.com or call us at (760) 744-0125.

Sincerely,

Sullins Connector Solutions