



Date: July 01, 2015

PRODUCT CHANGE NOTIFICATION #10032

Notification of: Part number discontinued with replacement.

Date Change Effective: July 01, 2015

Explanation of change (from, to): P/N NPBC__DFAN-RC, drawing 11252 rev C, will be discontinued and replaced with P/N _R_C__D__N-RC, drawing 11636 rev E.

Reason for change: Components or Materials used in discontinued part number are no longer available. New part number layout includes multiple configurations for header size.

Anticipated impact on fit, form, or function (positive/negative): Positive

Parts/Products affected:

.100 CC, dual row, male header, straight tail

Parts prior to change will remain active for purchase?

Yes ___ No X

New or revised parts are interchangeable to the previous part applications?

Yes X No ___

Engineering Approval:

(Signature)

Ken Stark

(Printed Name)

July 01, 2015

(Date)

Distribution: Website, Distributors, Customers, Internal

Information regarding this change notification and other previously issued change notifications can be found on our website: www.sullinscorp.com/techcenter. If you have any questions or concerns, please contact us at Support@sullinscorp.com or call us at (760) 744-0125.

Sincerely,

Sullins Connector Solutions