



Date: December 10, 2009

**PRODUCT CHANGE NOTIFICATION # 10034**

**Notification of:** Part number discontinued with replacement

**Date Change Effective:** January 15, 2010

**Explanation of change (from, to):**

Material change	<u>from</u>	<u>to</u>
	Black Thermoplastic polyester	Black Nylon
Part number change	<u>from</u>	<u>to</u>
	PRPN__1PAEN-RC	NRPN__1PAEN-RC (DWG 10531)
	PRPN__2PAEN-RC	NRPN__2PAEN-RC (DWG 10637)
	PRPN__1PARN-RC	NRPN__1PARN-RC (DWG 10654)
	PRPN__2PARN-RC	NRPN__2PARN-RC (DWG 10664)
	PRPN__4RCCN-RC	NRPN__4RCCN-RC (DWG 10734)
	PPPN__1BFCN-RC	NPPN__1BFCN-RC (DWG 10483)
	PPPN__2AFCN-RC	NPPN__2AFCN-RC (DWG 10497)
	PPRN__4EFCN-RC	NPRN__4EFCN-RC (DWG 10665)
	PPPN__4EFCN-RC	NPPN__4EFCN-RC (DWG 10665)
	PPPN__1FGGN-RC	NPPN__1FGGN-RC (DWG 10490)
	PPPN__2FJFN-RC	NPPN__2FJFN-RC (DWG 10461)

**Reason for change:** Material used in discontinued part number is no longer available.

**Anticipated impact on fit, form, or function (positive/negative):** Positive

**Parts/Products affected:** 2mm contact center male and female header series

**Parts prior to change will remain active for purchase?**

Yes \_\_\_ No x

**New or revised parts are interchangeable to the previous part applications?**

Yes x No \_\_\_

**Engineering Approval:**

  
**(Signature)**

Ken Stark  
**(Printed Name)**

Note: this PCN has been revised for clarity to replace PCN # 09001

Distribution: Website, Distributors, Customers, Internal

Information regarding this change notification and other previously issued change notifications can be found on our website: [www.sullinscorp.com/techcenter](http://www.sullinscorp.com/techcenter). If you have any questions or concerns, please contact us at [Support@sullinscorp.com](mailto:Support@sullinscorp.com) or call us at (760) 744-0125.

Sincerely,  
**Sullins Connector Solutions**