

Date: 05/26/2017

PRODUCT CHANGE NOTIFICATION #10040

Notification of: .100" & .156" contact center Male Edgecard Part Numbers discontinued with replacement.

Date Change Effective: May 19, 2017.

Explanation of change (from, to):

DISCONTINUED	REPLACED WITH	Drawing #
A_C__M(MR, MN)_	RMC__M(MR, MN)_	C11050
A_C__M(MW, MS, MM)_ L_C__M(MW, MS, MM)_	RMC__M(MW, MS, MM)_ G_C__M(MW, MS, MM)_-S2196	C11051
A_C__M(MA,MV,MB,MD,MJ,MK)_(OMIT, -S189)	RMC__M(MA,MV,MB,MD,MU,MK)_(OMIT, -S189)	C11052
A_C__M(MW, MS, MM)N-S1998	RMC__M(MM,MS,MW)N-S1998	C12781
A_M__M(MR,MN)_	RMM__M(MR,MN)_	C11074
A_M__M(MW,MS,MM)_	RMM__M(MW,MS,MM)_	C11075
A_M__M(MA,MV,MB,MD,MJ,MK)_(OMIT, -S189)	RMM__M(MA,MV,MB,MD,MJ,MK)_(OMIT, -S189)	C11076
A_M__M(MW,MS,MM)_-S1793	RMM__M(MW,MS,MM)_-S1793	C12414
A_M__MMM_-S1805	RMM__MMM_-S1805	C12441

Reason for change:

- (1) Contact Material Beryllium Copper used in discontinued part number ('A' material code) is replaced with Phosphor Bronze.
- (2) For consistency, part number coding 'L' replaced with 'G' without specification change.

Anticipated impact on fit, form, or function (positive/negative): Positive

Parts/Products affected: .100" & .156" Contact Center, Male Edgecard.

Parts prior to change will remain active for purchase?

Yes ___ No X

New or revised parts are interchangeable to the previous part applications?

Yes X No ___

Engineering Approval:



Truong Tran

05.26.17

(Signature)

(Printed Name)

(Date)

Distribution: Website, Distributors, Customers, Internal



Form
QF-7.3.7 Rev A
Date: 02/18/2015

Information regarding this change notification and other previously issued change notifications can be found on our website: www.sullinscorp.com/techcenter. If you have any questions or concerns, please contact us at Support@sullinscorp.com or call us at (760) 744-0125.

Sincerely,
Sullins Connector Solutions