



Date: July 01, 2015

**PRODUCT CHANGE NOTIFICATION #10032**

**Notification of:** Part number discontinued with replacement.

**Date Change Effective:** July 01, 2015

**Explanation of change (from, to):** P/N NPBC\_\_DFAN-RC, drawing 11252 rev C, will be discontinued and replaced with P/N \_R\_C\_\_D\_\_N-RC, drawing 11636 rev E.

**Reason for change:** Components or Materials used in discontinued part number are no longer available. New part number layout includes multiple configurations for header size.

**Anticipated impact on fit, form, or function (positive/negative):** Positive

**Parts/Products affected:**

.100 CC, dual row, male header, straight tail

**Parts prior to change will remain active for purchase?**

Yes \_\_\_ No X

**New or revised parts are interchangeable to the previous part applications?**

Yes X No \_\_\_

**Engineering Approval:**

(Signature)

Ken Stark

(Printed Name)

July 01, 2015

(Date)

Distribution: Website, Distributors, Customers, Internal

Information regarding this change notification and other previously issued change notifications can be found on our website: [www.sullinscorp.com/techcenter](http://www.sullinscorp.com/techcenter). If you have any questions or concerns, please contact us at [Support@sullinscorp.com](mailto:Support@sullinscorp.com) or call us at (760) 744-0125.

Sincerely,

**Sullins Connector Solutions**