

Date: 11/6/2017

**PRODUCT CHANGE NOTIFICATION #10042**

**Notification of:** .100" contact center Header Part Numbers obsolete

**Date Change Effective:** 11/6/2017

PART NUMBER OBSOLETE	DWG#	SIMILAR PART TO REPLACE WITH	DWG#
GR_C___S(AA, AB, AC, AD, AE, AF, AG, AH, AI, AJ, AK, FA, FB, FC, FD, FE, FF, FG, FH, FI, FJ, ZA, ZB, ZC, ZD, ZI, ZJ, ZO, ZQ, ZR)N-RC	11635	LR_C___S(AA, AB, AC, AD, AE, AF, AG, AH, AI, AJ, AK, FA, FB, FC, FD, FE, FF, FG, FH, FI, FJ, ZA, ZB, ZC, ZD, ZI, ZJ, ZO, ZQ, ZR)N-RC	11635
GR_C___D(AA, AB, AC, AD, AE, AF, AG, AH, AI, AJ, AK, FA, FB, FC, FD, FE, FF, FG, FH, FI, FJ, ZA, ZB, ZC, ZD, ZI, ZJ, ZO, ZQ, ZR)N-RC	11636	LR_C___D(AA, AB, AC, AD, AE, AF, AG, AH, AI, AJ, AK, FA, FB, FC, FD, FE, FF, FG, FH, FI, FJ, ZA, ZB, ZC, ZD, ZI, ZJ, ZO, ZQ, ZR)N-RC	11636
GR_C___D(BA, BB, BC, BD, BE, BH, BI, BJ, GA, GB, GE, GF)N-M71RC	11639	LR_C___D(BA, BB, BC, BD, BE, BH, BI, BJ, GA, GB, GE, GF)N-M71RC	11639
GR_C___S(AB,FB,ZS,ZT)_-M30RC	11657	LR_C___S(AB,FB,ZS,ZT)_-M30RC	11657
GR_C___D(AB,FB,ZS,ZT)N-M30RC	11658	LR_C___D(AB,FB,ZS,ZT)N-M30RC	11658
GR_C___S(BS,GS,ZC,ZU)N-M89RC	11659	G_C___S(BS,GS,ZC,ZU)N-M89	C10060
GR_C___S(BA, BB, BC, BD, BE, BF, BG, BH, BI, BJ, GA, GB, GC, GD, GE, GF, DA)N-RC	11638	G_C___S(BA, BB, BC, BD, BE, BF, BG, BH, BI, BJ, GA, GB, GC, GD, GE, GF, DA)N	C10909

**Parts prior to change will remain active for purchase?**

Yes \_\_\_ No X

**New or revised parts are interchangeable to the previous part applications?**

Yes X No \_\_\_

**Engineering Approval:**



Truong Tran

(Signature)

(Printed Name)

11/6/2017  
(Date)

Distribution: Website, Distributors, Customers, Internal

Information regarding this change notification and other previously issued change notifications can be found on our website: [www.sullinscorp.com/techcenter](http://www.sullinscorp.com/techcenter). If you have any questions or concerns, please contact us at [Support@sullinscorp.com](mailto:Support@sullinscorp.com) or call us at (760) 744-0125.

Sincerely,  
**Sullins Connector Solutions**