



801 E Mission Rd, San Marcos CA 92069 P: 760-744-0125 F: 760-744-6081 www.sullinscorp.com

FORM  
DOC QF-7.3.7 Rev –  
10/27/2010

**ENGINEERING CHANGE BULLETIN #10023**

**CUSTOMERS' NOTIFICATION OF PART MATERIAL CHANGE**

**Date Change Effective: 12/19/2014**

**Explanation of change from existing to new part number:**

The following product series have been upgraded with lower moisture absorption rate Nylon material:

- xPPNxx2FFKx-RC (DWG# C10485-J)
- xPPNxx1BHLx-RC (DWG# C11211-C)
- xPxNxx2FFKx-M81RC (DWG# C12048-B)

**Configuration impacts for fit, form, and function are:**

Upgrade Nylon material to Nylon with lower moisture absorption rate

**Existing parts will remain active for purchase?**

Yes  X  No    

**New or revised parts are interchangeable to the previous part applications?**

Yes  X  No    

**Engineering Approval:**

  
\_\_\_\_\_  
(Signature)

**Date: 12.19.2014**

**Ken Stark**  
\_\_\_\_\_  
(Printed Name)

**Distribution:**

**Sales/Purchasing/Manufacturing Operations, Quality Assurance/Document Control, Product Specialist, Molding, Kitting**