



801 E Mission Rd, San Marcos CA 92069 P: 760-744-0125 F: 760-744-6081 www.sullinscorp.com

FORM
DOC QF-7.3.7 Rev -
10/27/2010

ENGINEERING CHANGE BULLETIN #10016

CUSTOMERS' NOTIFICATION OF PART NUMBER CHANGE

Date Change Effective: 11/01/2013

Explanation of change from existing to new part number:

Nylon 46 is now obsolete.

CUSTOMERS' NOTIFICATION OF PART NUMBER CONFIGURATION REVISIONS

Date Change Effective: 11/01/2013

Explanation of configuration change/ (From) (To):

'N'(Nylon 46) material code removed, replaced by 'G'(Nylon 9T)

Changed from:

Changed to:

N_E__DHRQ-T94_ G_E__DHRQ-T94_ (DWG# 11042)

N_E__DHRN-T94_0 G_E__DHRN-T94_0 (DWG# 11043)

N_E__DHRN-T94_ G_E__DHRN-T94_ (DWG# 11044)

Existing parts will remain active for purchase? Yes ___ No X

'N' material code changed from Nylon 46 to Nylon 9T

N_E140DHHN-T9__ (DWG# 11040)

N_E115DHHN-T9__ (DWG# 11041)

N_E__DHHN-T9__ (DWG# 11045)


Existing parts will remain active for purchase? Yes X No ___

Configuration impacts for fit, form, and function are:

Upgrade in material. Improves processing

New or revised parts are interchangeable to the previous part applications?

Yes X No ___

Engineering Approval:  **Date:** 11/1/13
(Signature)

Distribution:

Sales/Purchasing/Manufacturing Operations, Quality Assurance/Document Control, Technical Support, Molding, Kitting