



SULLINS | MicroPlastics  
 760.744.0125 | fax 760.744.6081  
 801 E. Mission Rd.  
 San Marcos Ca. 92069  
<http://www.SullinsElectronics.com>  
<http://www.Micro-Plastics.com>

FORM  
 DOC QF-7.3.7 Rev –  
 10/27/2010

**ENGINEERING CHANGE BULLETIN**

**ECB#:** 10005

**DATE:** 5/12/2011

**CUSTOMERS' NOTIFICATION OF PART NUMBER CHANGE**

**Date Change Effective:** 5/12/2011

**Explanation of change from existing to new part number:**

Removed T1 from part number per EWR# 1263

**CUSTOMERS' NOTIFICATION OF PART NUMBER CONFIGURATION REVISIONS**

**Date Change Effective:** 5/10/2011

**Explanation of configuration change/ (From) (To):**

Part number on DWG# 11139 was changed from NRPC\_\_ \_\_ SAAN-T1RC to NRPC\_\_ \_\_ SAAN-RC

Part number on DWG# 11252 was changed from NRBC\_\_ \_\_ DFAN-T1RC to NRBC\_\_ \_\_ DFAN-RC

**Configuration impacts for fit, form, and function are:**

N/A

**Existing parts will remain active for purchase? Yes:  No**

**New or revised parts are interchangeable to the previous part applications?**

Yes:  No

**Engineering Approval:**

(Signature)

**Date:** 5/12/11

**Distribution:**

Sales/Purchasing/Manufacturing Operations, Quality Assurance/Document Control, Technical Support