



801 E Mission Rd | San Marcos, CA 92069

REFLOW SOLDER PROCESS INFORMATION FOR NYLON 6T PRODUCTS

Due to the high Moisture Absorption Rate, Sullins products using Nylon 6T insulator material are not intended for use in a Reflow Soldering Process. Wave or Manual Soldering is acceptable.

If Reflow Processing is needed, it is recommended to select an insulator material with a lower Moisture Absorption Rate, including but not limited to: Nylon 9T or LCP.

Sincerely,

Sullins Connector Solutions
Support@sullinscorp.com
760.744.0125